Docket No.

245841US2

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: Simon RYDER

SERIAL NUMBER: 10/722,527

ATTN: APPLICATION BRANCH

FILING DATE:

November 28, 2003

FOR:

A METHOD OF DIAGNOSING A FAULT ON A TRANSFORMER WINDING

## FILING OF SUPPLEMENTAL APPLICATION DATA SHEET

COMMISSIONER FOR PATENTS ALEXANDRIA, VIRGINIA 22313

SIR:

The attached Supplemental Application Data Sheet is submitted herewith to correct the mailing address, residence and citizenship of the inventor.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND, MAIER & NEUSTADT, P.C.

Customer Number

22850

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 05/03) I:\USER\MICKS\2458\245841us SUP ADS.DOC Registration No. 24,913

Joseph A. Scafetta, Jr.

Registration No. 26, 803